

**STANDARD FORM****MCC INSPECTION REGISTER****MAT-ASF-003**

Process Owner: Operations Superintendent

Status: Approved

Issued:

**19 February 2000****Alexandria Station Mineral Claim Inspection Register and Activities Record.**Inspected by: Mark Joraslafsky Date: December 1 2003

MCC NO:	DATUM	NW CORNER PEG	SE CORNER PEG	SW CORNER PEG	Activities since last annual check (Exploration, rehabilitation, material moved)
MCC 205	OK	OK	OK	OK	Nil
MCC 206	OK	OK	OK	OK	No material extraction.(Contains pit) pit full of water.
MCC 207 *	OK	OK	OK	OK	Weeds on stockpile sprayed
MCC 708	OK	OK	OK	OK	Nil
MCC 983	OK	OK	OK	OK	Nil
MCC 984	OK	OK	OK	OK	Nil
MCC 985	OK	OK	OK	OK	Nil
MCC 986	OK	OK	OK	OK	Nil
MCC 987	OK	OK	OK	OK	Nil
MCC 988	OK	OK	OK	OK	Nil
MCC 989	OK	OK	OK	OK	Nil
MCC 990	OK	OK	OK	OK	Some road repairs to gain access requires some fill to be carted in from mataranka quarry

Extra Comments: Road from tablelands highway in very poor condition with all grids protruding above ground so take care. All directional trenches will need to be re dug.

Tons of gypsum removed from site -Nil

**STANDARD FORM**

**MCC INSPECTION REGISTER**

**MAT-ASF-003**

Process Owner: Operations Superintendent

Status: Approved

Issued:

**19 February 2000**

---