



**EXPLOREMIN PTY. LTD.  
GEOLOGICAL CONSULTANTS**

ACN 010 629 884  
23 - 25 Waterfall Close  
EDMONTON 4869  
Cairns QLD

PO Box 229  
EDMONTON 4869

Phone: 61 7 4055 5138  
Fax: 61 7 4055 5136  
E-mail: [goulepl2@bigpond.com](mailto:goulepl2@bigpond.com)

3 April 2008

Northern Land Council  
GPO Box 1222  
DARWIN 0801

Attn: Mr Mark Rumler, Solicitor

Dear Mark

**Re: MLN 1155 "Future Act" RTN**

In accordance with undertakings made in the NNTT mediation conference on 1 April, in the matter of DM08/6 before Deputy President Sumner, we present herewith:

- a digital copy of the Feasibility Study completed in 2006 in respect of the Mt Bunday Gold project located on adjacent granted Mineral Lease 1083;
- a copy of the Executive Summary from that Feasibility Study;
- a copy of Section 17.7.2 from the Feasibility Study which describes the proposed tailings dam to be built on the area of MLN 1155;
- a location diagram which illustrates the spatial relationship between MLN 1083 and MLN 1155; and
- a diagram which illustrates the layout of the proposed developments on MLN 1155 (note that the access road and transmission line from the north have been in place for the past 14-15 years).

As stated in the original application documents and covering letter for MLN 1155 which were lodged with the Northern Territory Government on 20 December, 1996, MLN 1155 is required "for the purpose of a tailings disposal facility for Stage 2" development of the Rustlers Roost gold deposit on adjacent MLN 1083. This purpose was also stated in the Application for an AAPA "Authority Certificate" which was attached to the application for the mineral lease.

At the time of application in 1996, the mineral lease covered the areas of both Exploration Licence 9011 and granted Mineral Claims 2671-2683 held by Rustlers Roost Mining Pty Ltd. These earlier titles have all since been surrendered.

Past exploration has not identified any mineral resources on the area of MLN 1155 and no mining is proposed for the area of the lease.

While most of the matters raised in your letter on 12 December, 2007, are more relevant to the area of granted ML 1083 (and addressed to varying degrees in the Feasibility Study) than to the area of MLN 1155, we will, nevertheless, respond to your requests in respect of the issues which directly affect the area of MLN 1155 in separate correspondence.

Yours Faithfully

**EXPLOREMIN PTY LTD**



**John Goulevitch**


**MANAGING DIRECTOR**

BSc(Hons) MSc FAIG


cc: National Native Title Tribunal, Darwin  
Director of Titles, NT-DPIFM  
Rustlers Roost Mining Pty Ltd, Toronto, Canada

Incl:  
GBS Feasibility Study and Appendices CD  
Feasibility Study Summary and extracts  
Rustlers Roost location and tenure diagram  
Proposed development layout diagram









REVISIONS				NOTES			
NO	DATE	DESCRIPTION	BY	CHKD	1-DIMENSIONS IN mm	2-DIMENSIONS IN mm	3-DIMENSIONS IN mm
0	01/01/00	PRELIMINARY	A	11	11	11	11
1	01/01/00	GENERAL REVISION	A	11	11	11	11
2	01/01/00	GENERAL REVISION	A	11	11	11	11
3	01/01/00	CONFORM CLIENT COMMENTS	A	11	11	11	11
4	01/01/00	WASTE DUMP/PIT DESIGNS	A	11	11	11	11
5	01/01/00	INCLUSION	A	11	11	11	11

NUMBER	TITLE
FIGURE 2	GREENHOUSE REPORT-1997

RESPONSIBLE	NAME	DATE
PROJECT	DEF	2001/12/01
DESIGN	AL	2001/12/01
CHECKING	B	2001/12/01
SUPERVISOR	SD	2001/12/01
COORDINATOR	JD	2001/12/01

TYPE OF ISSUE	DATE
(1) PRELIMINARY	2001/12/01
(2) FOR INFORMATION	2001/12/01
(3) FOR COMMENTS	2001/12/01
(4) FOR APPROVAL	2001/12/01
(5) FOR QUOTATION	2001/12/01
(6) FOR CONSTRUCTION	2001/12/01
(7) FOR PURCHASE	2001/12/01

VALENCIA VENTURES INC.		DATE	11/01/00
TITLE:		MT. BUNDY PROJECT FEASIBILITY STUDY GENERAL LOCATION-SITE DETAILS	
DRAWING N°		GEST-091-000-102-DS-002	

LAYER
RED-0.10
YELLOW-0.2
GREEN-0.3
CYAN-0.4
BLUE-0.5
MAGENTA-0.6
BLACK-0.7
COR 8-0.10