

EXOIL (N.T.) PTY. LTD.

WELL COMPLETION REPORT


EAST JOHNNY'S CREEK NO. 1

by

N. R. McTaggart and D. D. Benbow

OPEN FILE

Also relates to Re 82/47A

 PR 65 17/B.

	<u>Page</u>	<u>Sect.</u>
Summary	(i)	1
Resume of Drilling Operations	(ii)	1
Introduction	(ii)	1
Well History:		
General and Drilling Data	1	1-2
Logging and Testing	4	3-6
Geology:		
Summary of Previous Work	8	7
Regional Stratigraphy	9	8
Formations Penetrated	12	8
Structure	17	9
Relevance to Occurrence of Petroleum ...	17	10
Porosity and Permeability of Sediments Penetrated	18	11

APPENDICES

Appendix 1	Core Descriptions by D. D. Benbow	12
Appendix 2	D.S.T. Reports by D. D. Benbow	13
Appendix 3	Water Analyses by Northern Territory Administration	14
Appendix 4	Petrological Reports by W. B. Bryan	15
Appendix 5	X-radiography - Core 7 by Australian Mineral Development Laboratories	16
Appendix 6	Core Analyses by Core Laboratories Inc.	17

ILLUSTRATIONS

Frontispiece	Photograph showing glauconite grains in cuttings Illara Sandstone, East Johnny's Creek No. 1	contents
--------------	--	----------

Figure

1	Location Map	18
2	Time Versus Depth Graph	2
3	Pressure Chart - D.S.T. No. 1	5
4	Pressure Chart - D.S.T. No. 2	5
5	Regional Geology - East Johnny's Creek No. 1	19
	Composite Well Log - at back of report	20