



Document Title	<h2>Well Completion Report</h2> <h3>GLYDE #1 ST1, EP171</h3> <h3>McArthur Basin</h3> <h3>Northern Territory, Australia</h3>
Document Number	EP171_XPN-DRL-PRP-007-RevD

Rev	Status	Prepared by	Checked by	Approved By	Date
D	Final	Christine Eickhoff 			11/02/13
D	Final			Luke Titus 	11/02/13

<b>Document Title</b>	Well Completion Report, GLYDE #1 ST1, EP171
-----------------------	---

## Table of Contents

1.	WELL SUMMARY & GENERAL DATA .....	4
2.	DRILLING .....	5
2.1.	Drilling Summary .....	5
2.2.	Equipment Installed in or on the Well .....	6
2.3.	Wellbore schematic GLYDE #1 ST1 .....	8
2.4.	Casing and Equipment Installed in or on the Well .....	9
2.5.	Deviation Survey .....	9
2.6.	Cementing Operation .....	13
2.7.	Bit Record .....	14
2.8.	Drilling Fluids .....	14
3.	FORMATION EVALUATION .....	15
3.1.	Depth and Types of Cores and Cuttings, Well Evaluation Log and Fluid Samples .....	15
3.1.1.	Drill Cores .....	15
3.1.2.	Cuttings .....	15
3.1.3.	Well evaluation logs .....	18
3.1.4.	Fluid samples .....	19
3.2.	Hydrocarbon Indications .....	19
3.3.	Operation and Results including full raw pressure-time listings for all formation fluid sample tests and production tests carried out .....	19
4.	GEOLOGY .....	27
4.1.	Pre-Spud Geological Well Prognosis .....	27
4.2.	Along Hole and True Vertical Depth of Seismic Marker and Reservoir Horizons ....	27
4.3.	Geological Interpretation of the Well Data .....	27
4.3.1.	Log Adjusted Lithology Description .....	28
4.3.2.	Reservoir Quality .....	30
4.3.3.	Source Rock Quality .....	30
4.3.4.	Hydrocarbon Indications .....	30
4.3.5.	Trap integrity .....	34
4.4.	Discussion of the relevance of the Well Data to the Evaluation of the Hydrocarbon Potential of the Area .....	34
	APPENDICES .....	39

<b>Document Title</b>	Well Completion Report, GLYDE #1 ST1, EP171
-----------------------	---

## Table of Figures

Figure 1: Wellbore Schematic for GLYDE #1 ST1, EP171.....	8
Figure 2: True vertical depth (TVD) plotted against vertical section at GLYDE #1 ST1.....	11
Figure 3: Measured depth (MD) and true vertical depth (TVD) plotted against vertical section at GLYDE #1 ST1.....	11
Figure 4: GLYDE #1 ST1 EP171, directional drilling information from Pathfinder.....	12
Figure 5: Fekete's WellTest™ Version 7.5.2.211 reservoir parameters.....	22
Figure 6: GIP reservoir parameters.....	23
Figure 7: Flow test (646 m - 689 m).....	24
Figure 8: Radial curve (646 m - 689 m).....	25
Figure 9: Type curve (646 m - 689 m).....	26
Figure 10: Glyde #1 ST1, measured depth log showing dolomitic density-neutron 'gas-effect' and associated gas kick at the top of the Breccia Coxco Member.....	31
Figure 11: Glyde #1 and Glyde #1 ST1, measured depth cross-section and associated gas shows with 'hot' gamma readings in the Barney Creek Formation.....	32
Figure 12: Glyde #1 ST1, major show interval on mudlog; first gas 10/08/2012 at 0530 hrs.....	33
Figure 13: Location Map of the 'Glyde 1 Gas Accumulation' of the 'Greater Coxco Field' in the Glyde Sub-Basin.....	35
Figure 14: Glyde #1 ST1 gas flare at 756 mMD.....	38
Figure 15: Location of the Greater Coxco Field in the Glyde Sub-Basin.....	39

## Table of Tables

Table 1: Deviation survey for vertical drilling at GLYDE #1 ST1, EP171.....	9
Table 2: Deviation survey for directional drilling at GLYDE #1 ST1, EP171 (Commence side track at 250.02 m).....	9
Table 3: Bit Record for GLYDE #1 ST1, EP171.....	14
Table 4: Shut-in Casing Pressures.....	19
Table 5: Flow Test Data.....	20
Table 6: Geologic description of the formations.....	27
Table 7: Well log formation tops for GLYDE #1 ST1, EP171, TD = 840 m.....	27
Table 8: Clause 553, Sub-Clause 4 "Probability Table 1". Part B- 'Glyde 1 Gas Accumulation'.....	36
Table 9: Reservoir Assumptions.....	37